



DONALDSON


$$4009 \overline{) 99}$$

DWG PG # 1
04870- P22


0674119-050101



PAGE #2
04870- P22



NOV 9/99

09741119.052101




DWG PAGE
#3 04870-P22

0074119-052101
FOI250-5114260







PWG PAGE
4
P-22 04870-P22




DWG PAGE 15

04870-P22.

0974119.052101




0974119-052101




DWG PG - 6
04870-P22

09741139-052101



04820-P22 DWG PAGE 7

FIG. 19



Dwg Page 8
04870-P22

00741119.052101






FIG 25A,

DWG PAGE 9
04870-P22

09744119.052101



DRAWING PAGE
10 04870-P22






FIG. 28




DWG PAGE
11 04870-P22

0974113-052101



DRAWING
04870-P22 PAGE 12

04870-053101



DWG PAGE 19

04870-P22